

---

Dane aktualne na dzień: 27-04-2026 09:35

Link do produktu: <https://darmotsc.pl/filtr-kabinowy-sc-50022-zamienniki-h-816810140070-h-816810140071-h-916810140070-cu-4197-p-1105.html>



## Filtr kabinowy SC 50022 - Zamienniki: H 816810140070, H 816810140071, H 916810140070, CU 4197

Cena brutto	<b>72,57 zł</b>
-------------	-----------------

Cena netto	<b>59,00 zł</b>
------------	-----------------

Numer katalogowy	<b>1229</b>
------------------	-------------

### Opis produktu

#### Zastosowanie:

**Fend:** 307 C, 307 C Turbo, 307 CA, 307 CI, 307 Turbo, 308 C, 308 C Turbo, 308 CA, 308 CI, 308 Turbo, 309 C Turbo, 309 CA, 309 Turbo, 309 Turbo, 309 Vario, 310 Turbo, 310 Vario, 311 Turbo, 311 Vario, 312 Turbo, 312 Vario, 409 Vario, 410 Vario, 411 Vario, 412 Vario, 413 Vario, 414 Vario, 415 Vario, 509 C, 510 C, 511 C, 512 C, 512 CA, 514 C, 514 CA, 515 C, 711 Vario, 712 Vario, 714 Vario, 716 Vario, 718 Vario, 815 Vario TMS, 816 Vario Turbo, 817 Vario TMS, 818 Vario, 818 Vario Turbo, 822 Vario Turbo, 824 Vario Turbo, 916 Vario, 920 Vario, 924 Vario, 926 Vario, 930 Vario, 370 GT, 370 GTA, 380 GTA Turbo, 395 GHA, 395 GTA, 520, 522, 524