

Link do produktu: <https://darmotsc.pl/filtr-oleju-hydraulicznego-sh-63061-zamienniki-89811117-3i1497-azh393-p550268-hf6173-84818750-89811117-32902301-32902301-p-1102.html>



Filtr oleju hydraulicznego SH 63061 - Zamienniki: 89811117, 3I1497, AZH393, P550268, HF6173, 84818750, 89811117, 32/902301, 32902301

Cena brutto	43,05 zł
Cena netto	35,00 zł
Numer katalogowy	1226

Opis produktu

Zastosowanie:

Ford New Holland: FX28, FX30, FX375, FX38, FX40, FX450, FX60, FX45, FX58

JCB: 926, 930, 940, 407, 525-58, 525-67, 530-110, 530-120, 530-67, 530-70, 530-95, 530B-2, 530B-4, 535-67, 540BM-2, 540BM-4, 530, 505-19, 505-22, 506 B, 506-36, 525-50, 530 B, 530 B2, 530 B4, 530-120 Turbo, 531-70, 533-105, 533-105 B, 533-105 Telebat T, 535-95 Telebat, 535-95 Telebat CD, 536-60, 540 B2, 540 BM2, 541-70, TH525-58 ATMO, TH525-58 FS - ATMO, TH525-58 FS - Turbo, TH525-58 Turbo, TH525-67 ATMO, TH525-67 FS - ATMO, TH525-67 FS - Turbo, TH525-67 Turbo, TH527-58, TH527-58 FS, TH527-67 ATMO, TH527-67 FS - ATMO, TH527-67 FS - Turbo, TH527-67 Turbo, TH530 B - ATMO, TH530 B Turbo, TH530 BHL - ATMO, TH530 BHL Turbo, TH530 FS - ATMO, TH530 FS - Turbo, TH530 S - ATMO, TH530 S Turbo, TH530-120 ATMO, TH530-120 Turbo, TH530-67 ATMO, TH530-67 FM - ATMO, TH530-67 FM - Turbo, TH530-67 Turbo, TH530-95 ATMO, TH530-95 Turbo, TH535-67 ATMO, TH535-67 Turbo, TH540 ATMO, TH540 B - ATMO, TH540 B Turbo, TH540 BM - ATMO, TH540 BM Turbo, TH540 FS - ATMO, TH540 FS - Turbo, TH540 Turbo