

---

Dane aktualne na dzień: 16-05-2026 22:42

Link do produktu: <https://darmotsc.pl/filtr-oleju-so-6105-zamienniki-sp43021-sp-40321-lf-3657-b-7487-p-1074.html>



## Filtr oleju SO 6105 - zamienniki: SP4302/1, SP 40321, LF 3657, B 7487

|                  |                 |
|------------------|-----------------|
| Cena brutto      | <b>24,60 zł</b> |
| Cena netto       | <b>20,00 zł</b> |
| Numer katalogowy | <b>1197</b>     |

### Opis produktu

**Zastosowanie:** Iseki TX 1000, TX 1210, TX 1300, TX 1410, TX 1500, TX 2140, TX 2160, Landini Mistral 40, Mistral 45, Mistral 50, Weidemann 811, 911, 912, 916, 917, 1002, 1702, 1802, 2002